

# ATTENTION

THIS BULLETIN INCLUDES INFORMATION ABOUT A NEW OR EXISTING OPTION OR FEATURE THAT IS AVAILABLE FOR PRODUCTION.

DESCRIPTION: Chassis Issues

PLANT: Rosenbauer

SPECIFICATION: Please be aware of the following:

- When selling a unit with the safety restraint system, which includes side air bags and seatbelt tensioning systems, it is extremely difficult and expensive to add seats at a later date. Additional seats can cost upwards of \$25,000 for two as the truck needs to be rewired to accommodate the sensors. Be sure to clarify and confirm the number and placement of seats.
- We also recommend that to meet the 2009 NFPA requirements for roll stability that all aerials with custom chassis be equipped with a Roll Stability Control system. With this system a tilt table test is not required. It is also recommended that all custom chassis tankers be equipped with this as well.